

MODERN EXPO

MAGELLAN

ASSEMBLY INSTRUCTIONS

Modern Expo thanks you for choosing our products

© All rights are reserved. Any reproduction of these materials is possible only with reference to the Modern Expo. 2024


TOOLS



Wrench 17-19 mm



Mallet




Screwdriver



Waterpass



Turn-screw




Allen wrench




Marker


INSTALLATION KIT




Screw din 967, type pz




Screw B007




Screw, type ph




Anchor




Screw din 7962, type ph




Nut din 6923



Self-tapping screw din 7504m,
type ph




Cap nut din 1587



Self-tapping screw din 7504,
type ph


Be sure to read the technical catalog before installation and operation.

STEP 1




pic. 1


STEP 2



pic. 2




STEP 3



pic. 3



STEP 4



pic. 4



pic. 4.1

STEP 5



pic. 5

STEP 6




pic. 6

STEP 7





The surface on which the checkout counters will be installed must be flat without differences in height.



If the checkout counter is installed on an uneven surface, the product may not work correctly.





pic. 7





STEP 8





pic. 8




STEP 9





STEP 10




STEP 11




pic. 11




STEP 12




pic. 12





STEP 13



STEP 14





STEP 15





pic. 15

STEP 16





pic. 16

STEP 17




pic. 17

STEP 18




pic. 18


STEP 19





pic. 19.1





pic. 19




STEP 20





pic. 20




STEP 21





pic. 21




STEP 22



pic. 22




STEP 23




pic. 23

STEP 24




pic. 24


STEP 25




pic. 25








STEP 26






pic. 26




STEP 27






STEP 28




STEP 29




pic. 29





STEP 30




pic. 30





pic. 30.1




STEP 31






pic. 31





STEP 32



pic. 32




STEP 33



pic. 33


pic. 33.1

STEP 34




pic. 34


ELECTRICITY



STEP 1 (A)




pic. 1 (A)





pic. 1.1 (A)

CABLELAYING DIAGRAM IN THE CHECKOUT COUNTER




- 1 - Power cable for the electric motor (KVAEFA.001.000)
- 2 - Electromagnetic switch with cable (KVAEEC.001.000)
- 3 - Photoelectric sensors with connectors
- 4 - «PE» drive (KVAEHA.001.000) to be connected to the electrical panel
- 5 - Conveyor control unit (KVAEAE.001.000)
- 6 - Power cable for the control unit (KVAEBC.001.000)

CONTROL UNIT FOR CONVEYOR GC-508



5




GC-508

1. Power connector XP1, control unit
2. Power connector Light, lighting
3. Power connector M1, motor power supply
4. Fuse, 3.15 A 230V
5. ON/OFF switch AC230V
6. 2-pin connector, electromagnetic switch
7. 4-pin connector, photoelements
8. 2-pin connector, foot pedal


MAGELLAN MINI

STEP 1






pic. 1



STEP 2



pic. 2





STEP 3




pic. 3

STEP 4




pic. 4


STEP 5 (A) For short checkout counters




pic. 5 (A)





STEP 5 (A1) For short checkout counters




pic. 5 (A1)




pic. 5.1 (A1)




STEP 6 (B) For long checkout counters




pic. 6 (B)



STEP 6 (B1) For long checkout counters



pic. 6 (B1)




STEP 7




The surface on which the checkout counters will be installed must be flat without differences in height.


If the checkout counter is installed on an uneven surface, the product may not work correctly.




pic. 7






STEP 8




pic. 8



pic. 8.1





STEP 9




pic. 9

STEP 10





pic. 10


STEP 11 (A) For short checkout counters





pic. 11 (A)




STEP 11 (B) For long checkout counters




pic. 11 (B)




STEP 11 (B1) For long checkout counters




pic. 11 (B1)




STEP 12





pic. 12



pic. 12.1






STEP 13



pic. 13




STEP 14



pic. 14



pic. 14.1

STEP 15




pic. 15

STEP 16




pic. 16


STEP 17




pic. 17



pic. 17.1



STEP 18



pic. 18



Head Office
Modern Expo Lutsk, Ukraine

T +380 (332) 78 95 00
info@modern-expo.com
modern-expo.eu

